DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

99.28 File #:

WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-028457 Address: 333 Burma Road **Date Inspected:** 18-Sep-2012

City: Oakland, CA 94607

OSM Arrival Time: 600 **Project Name:** SAS Superstructure **OSM Departure Time:** 1430 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

American Bridge Manufacturing Contractor: **Location:** Reedsport, OR

CWI Name: Jim Vanek **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Weld Procedures Followed: Electrode to specification:** Yes No Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** Hinge A Restraint Brackets

Summary of Items Observed:

This Quality Assurance Inspector (QAI), Dan Chang, performed a verification magnetic particle test (MT) on six restraint brackets (10% of total) piece-marked as: X01B-1, X01B-3, X01B-5, X01B-6, X01B-7, and X01B-8. The fillet welds of restraint brackets were tested by magnetic particle utilizing a yoke with dry red powder for visual contrast. The fillet welds appeared to be in general conformance with the contract documents at the time of review. It was noted that Welding Quality Control Inspector (QCI), Harry Woodward, of American Bridge Manufacturing (ABM) had previously performed magnetic particle tests on all 32 restraint brackets. Please refer to 04-0120F4 TL6028 B344 9-18-12 Reedsport report for more information.



WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Summary of Conversations:

No conversation regarding MT testing by this QAI.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas, 916-764-6027, who represents the Office of Structural Materials for your project.

Inspected By:	Chang,Dan	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer